



181114340087

# 检测报告



扫描全能王 创建

# 检测报告

浙化检字：2020T110C 号

样品名称：土壤（氰化物）  
委托单位：嘉兴市金鹰电镀有限公司  
受检单位：嘉兴市南湖区 3304021330117 地块  
检测性质：委托检测

浙江省化工产品质量检验站有限公司

2020年7月3日



扫描全能王 创建

样品编号	来样编号	采样日期 来样日期	氰化物 (mg/kg)
2020T110C-1	8988384723791	2020.06.07 2020.06.07	MDL:0.01 0.05
2020T110C-2	5342321218084	2020.06.07 2020.06.07	0.81
2020T110C-3	6282874794682	2020.06.07 2020.06.07	0.03
2020T110C-4	6855998258791	2020.06.07 2020.06.07	ND
2020T110C-5	6077709230262	2020.06.07 2020.06.07	0.04
2020T110C-6	7249563724103	2020.06.07 2020.06.07	ND
2020T110C-7	6961276308194	2020.06.07 2020.06.07	0.04
2020T110C-8	5390348599294	2020.06.07 2020.06.07	0.51
2020T110C-9	7521913627664	2020.06.07 2020.06.08	11.26
2020T110C-10	6002912448823	2020.06.07 2020.06.08	15.08





样品编号	来样编号	采样日期 来样日期	氰化物 /(mg/kg)
2020T110C-11	8842542267071	2020.06.07 2020.06.08	MDL:0.01 1.51
2020T110C-12	4673749377297	2020.06.07 2020.06.08	ND
2020T110C-13	8001110188387	2020.06.07 2020.06.08	ND
2020T110C-14	6415471646571	2020.06.07 2020.06.08	0.01
2020T110C-15	8413991725202	2020.06.07 2020.06.08	ND
2020T110C-16	5891323372812	2020.06.07 2020.06.08	0.01
2020T110C-17	5873140547891	2020.06.07 2020.06.08	0.07
2020T110C-18	9131443359032	2020.06.07 2020.06.08	0.04
2020T110C-19	7642770266295	2020.06.07 2020.06.08	0.05
2020T110C-20	5860531010533	2020.06.07 2020.06.08	0.03

